

HISTORIC AMERICAN BUILDING SURVEY

INDEX TO PHOTOGRAPHS

HABS
ARIZ
10-TUCSON
32C-

Tucson Plant Materials Center, General Utility Building (Bldg. No. 2) HABS No. AZ-159-C
3241 North Romero Road
Tucson
Pima County
Arizona

Jim Woodward, Photographer December 1993 (AZ-159-C-1 through AZ-159-C-7)

- | | |
|------------|---|
| AZ-159-C-1 | UTILITY BUILDING WEST FRONT AND SOUTH WALL,
LOOKING NORTHEAST. |
| AZ-159-C-2 | UTILITY BUILDING WEST FRONT AND NORTH WALL,
LOOKING SOUTHEAST. |
| AZ-159-C-3 | UTILITY BUILDING EAST AND SOUTH WALLS,
LOOKING NORTHWEST. |
| AZ-159-C-4 | UTILITY BUILDING SOUTH WALL, LOOKING NORTH. |
| AZ-159-C-5 | UTILITY BUILDING TYPICAL 12-LIGHT STEEL SASH AWNING
WINDOW. |
| AZ-159-C-6 | UTILITY BUILDING EXTERIOR VIEW OF TYPICAL WOOD PANEL
OVERHEAD GARAGE DOOR. |
| AZ-159-C-7 | UTILITY BUILDING INTERIOR VIEW OF WOOD PANEL OVER-
HEAD GARAGE DOORS, LOOKING NORTHWEST. |

Note: For photocopies of historic photographs showing contextual views of the site, see photographs for Tucson Plant Materials Center, HABS No. AZ-159.

Note: For additional written descriptive information, see narrative report for Tucson Plant Materials Center, HABS No. AZ-159.